



Figure 2b: Schematic diagram of detector element with leg isolation









collectors.

3/6





4/6




Figure 6a: Illustrating the effects of signal loss for non-normal incidence radiation.




Figure 6b: Coating the upper regions of the reflector array will tend to allow the radiation to be reflected deeper into the collector cavity.




Figure 6c: Placing a moulded lens array in front of the cavities will tend to pull high incidence angle radiation into a more-glancing angle of incidence onto the silicon surface, improving overall collector efficiency.



